## RAILROAD COMMISSION OF TEXAS HEARINGS DIVISION

OIL & GAS DOCKET NO. 20-0281622

# IN RE: P-5 ORGANIZATION REPORT OF TEJONES OPERATING CORPORATION

#### **FINAL ORDER**

The Commission finds that after notice and an opportunity for hearing regarding the captioned matter, the Operator failed to request a hearing and pay the hearing fee as required by 16 Tex. ADMIN. CODE §3.15(g)(4) and Tex. Nat. Res. Code §89.022(f). This matter having been duly submitted to the Railroad Commission of Texas at conference held in its offices in Austin, Texas, the Commission makes the following findings of fact and conclusions of law.

### **FINDINGS OF FACT**

- 1. Tejones Operating Corporation [Operator #841338] (the "Operator"), is the record operator or one or more inactive wells in the State of Texas and is required to file Organization Report (Form P-5) with the Commission. Operator's most recent P-5 was due on or before November 1, 2012.
- 2. After filing its most recent Organization Report (Form P-5) with the Commission, the Operator was notified they were deficient and had failed to comply with the requirements of 16 Tex. ADMIN. Code § 3.15 (Surface Equipment Removal Requirements and Inactive Wells) and provided with a written statement of the reasons for the determination and allowed ninety (90) days from the date its P-5 was due to comply with the requirements of 16 Tex. ADMIN. Code § 3.15 and Tex. Nat. Res. Code §§89.021 89.030.
- 3. After the expiration of ninety (90) days and pursuant to 16 Tex. ADMIN CODE §3.15(g)(4), an authorized Commission employee determined that the Operator's Organization Report still could not be renewed because the Operator continued to fail to comply with the requirements of 16 Tex. ADMIN. CODE §3.15 (Surface Equipment Removal Requirements and Inactive Wells).
- 4. The Commission sent the Operator a letter by certified mail giving notice to the Operator of the determination of continued non-compliance regarding specified inactive wells, attached as Exhibit A to this order, and advising the Operator of the right to request a hearing to show compliance. The letter notified the Operator that the hearing request must be received in docket services no later than 30 days after the date of the letter. The letter also notified the Operator that a final order denying renewal of the Operator's Organization Report (Form P-5) would result in the cancellation of all P-4 Certificates of Compliance and the severance of all pipeline or other carrier connections.

- 5. All notices and letters from the Commission to the Operator on this matter were addressed and mailed to the Operator's most recently reported address on the Form P-5 Organization Report.
- 6. The Operator did not timely request a hearing and pay the hearing fee on these issues as required under 16 Tex. ADMIN. CODE §3.15(g)(4) (Surface Equipment Removal Requirements and Inactive Wells).
- 7. Statewide Rule 15 (16 Tex. ADMIN. CODE §3.15) is a Commission rule that relates to safety or the prevention or control of pollution.

#### **CONCLUSIONS OF LAW**

- 1. The Operator received proper notice and an opportunity for hearing regarding compliance with 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 89.030.
- 2. All things necessary to the Commission attaining jurisdiction over the subject matter and the parties in this matter have been performed or have occurred.
- 3. The Operator is in violation of Commission Statewide Rule 15 and did not timely request a hearing to contest the determination that it was in violation.
- 4. The Operator's P-5 Organization Report should not be renewed and all of the Operator's P-4 Certificates of Compliance should be cancelled, with all related pipeline or other carrier connections severed. 16 Tex. Admin. Code §3.15 (g)(4) and Tex. Nat. Res. Code §§89.022(f), 91.704 91.706.
- 5. The Operator's P-5 Organization Report cannot be renewed until the operator brings the inactive wells shown on the attached Exhibit A into compliance with the requirements of 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 89.030.

IT IS ORDERED that renewal of Tejones Operating Corporation's P-5 Organization Report is hereby DENIED.

It is further ORDERED that all P-4 Certificates of Compliance issued to Tejones Operating Corporation as operator of record are hereby CANCELLED and all related pipeline or other carrier connections are hereby SEVERED.

It is further ORDERED that Tejones Operating Corporation shall bring the wells on Exhibit A into compliance with Statewide Rule 15 (16 Tex. ADMIN. CODE §3.15) and that the Operator's P-5 Organization Report shall not be renewed until the wells on Exhibit A have been brought into compliance as required by this order.

It is further ORDERED that Tejones Operating Corporation and each person who held a position of ownership or control in the Operator at the time the Operator's most-recent P-5 Organization Report was filed shall be subject to the terms of Tex. Nat. Res. Code §91.114.

It is further ORDERED by the Commission that this order shall not be final and effective until 20 days after a party is notified of the Commission's order. A party is presumed to have been notified of the Commission's order three days after the date on which the notice is actually mailed. If a timely motion for rehearing is filed by any party at interest, this order shall not become final and effective until such motion is overruled, or if such motion is granted, this order shall be subject to further action by the Commission. Pursuant to Tex. Gov't. Code §2001.146(e), the time allotted for Commission action on a motion for rehearing in this case prior to its being overruled by operation of law, is hereby extended until 90 days from the date the parties are notified of the order.

All requested Findings of Fact and Conclusions of Law which are not expressly adopted herein are **DENIED**. All pending motions and request for relief not previously granted or granted herein are **DENIED**.

#### **RAILROAD COMMISSION OF TEXAS**

(Signatures affixed by Rule 15 Inactive Well Master Order dated May 7, 2013.)

1

1

Docket No. 20-0281622

Exhibit A

2

API Number District ID Number Lease Name Well Number 029 37529 11686 POOLE 16 Electricity must be disconnected (certify on Form W-3C) Production fluids must be purged (certify on Form W-3C) No approved W-3X on file Must resolve Field Operations issue preventing 14(B)(2) approval Must resolve Field Operations H-15 delinquency preventing 14B2 approval Must resolve lack of Good Faith Claim issue preventing 14(B)(2) approval 029 37571 11686 POOLE 12 Electricity must be disconnected (certify on Form W-3C) Production fluids must be purged (certify on Form W-3C) No approved W-3X on file Must resolve Field Operations issue preventing 14(B)(2) approval Must resolve Field Operations H-15 delinquency preventing 14B2 approval Must resolve lack of Good Faith Claim issue preventing 14(B)(2) approval 029 37572 01 11686 POOLE 13 Electricity must be disconnected (certify on Form W-3C) Production fluids must be purged (certify on Form W-3C) No approved W-3X on file Must resolve Field Operations issue preventing 14(B)(2) approval Must resolve Field Operations H-15 delinquency preventing 14B2 approval Must resolve lack of Good Faith Claim issue preventing 14(B)(2) approval 029 37574 01 11686 POOLE 15 Electricity must be disconnected (certify on Form W-3C) Production fluids must be purged (certify on Form W-3C) No approved W-3X on file Must resolve Field Operations issue preventing 14(B)(2) approval Must resolve Field Operations H-15 delinquency preventing 14B2 approval Must resolve lack of Good Faith Claim issue preventing 14(B)(2) approval 029 37577 11686 POOLE Electricity must be disconnected (certify on Form W-3C) Production fluids must be purged (certify on Form W-3C) No approved W-3X on file Must resolve Field Operations issue preventing 14(B)(2) approval Must resolve Field Operations H-15 delinquency preventing 14B2 approval Must resolve lack of Good Faith Claim issue preventing 14(B)(2) approval 029 37608 APPLEWHITE, SAM 11714 1 Electricity must be disconnected (certify on Form W-3C) Production fluids must be purged (certify on Form W-3C) No approved W-3X on file Must resolve Field Operations H-15 failure preventing 14(B)(2) approval 029 37609 APPLEWHITE, SAM 11714 18 Electricity must be disconnected (certify on Form W-3C) Production fluids must be purged (certify on Form W-3C) No approved W-3X on file 029 37610 11714 APPLEWHITE, SAM 9 Electricity must be disconnected (certify on Form W-3C) Production fluids must be purged (certify on Form W-3C) No approved W-3X on file Must resolve Field Operations H-15 failure preventing 14(B)(2) approval

API	Number	District	ID Number	Lease Name		Well Number
029	No approx	ved W-3X on	disconnecte ust be purge	APPLEWHITE, Sid (certify on ) d (certify on )	Form W-3C) Form W-3C)	13
000					eventing 14(B)(2)	approval
029	No approv	red M-3% on	disconnecter ust be purger file	APPLEWHITE, SI i (certify on I i (certify on I	M	6
029	37614	01				approval
	Electrici Production	ty must be on fluids m red W-3X on	disconnected st be purged	APPLEWHITE, SE i (certify on F i (certify on F -15 failure pre	3 **	11
029	37615	01				approvat
<b>4</b> )	Electrici Production	ty must be n fluids mu	disconnected st be purged	APPLEWHITE, SA l (certify on F l (certify on F	'orm W-3C)	10
		ive Field C	perations H-	15 failure pre	venting 14(B)(2)	approval
029	No approv	ed M-3% on	disconnected st be purged	APPLEWHITE, SA (certify on F (certify on F		12
029	37617	01				approvat
	No approve	ty must be n fluids mu ed W-3X on	disconnected st be purged	APPLEWHITE, SAI (certify on Fo (certify on Fo 15 failure pres		7
	37618	01	11714	ADDI PRITTERS CO.		
	No approve	TIUIUS MU	disconnected st be purged	(certify on Fo	orm W-3C)	3
		rve kleta O	perations H-	15 failure prev	venting 14(B)(2)	approval
	No approve	TIUIUS IIIU	disconnected st be purged	APPLEWHITE, SAM (certify on Fo		5
	37620	01				approval
	Electricit Production No approve	y must be of fluids must be of W-3X on the	disconnected st be purged	APPLEWHITE, SAM (certify on Fo (certify on Fo .5 failure prev		4
129	37621	01	11714 2	DDT.PWHTMM GAM		
	No approve	truros mus	disconnected at be purged	(certify on Fo		2
				- rerrere brev	enting 14(B)(2) a	pproval

4